| Scope of Work for Property Located at: | | | | | | | 2475-77 North 40th Street | | |
|--|----------------------|--------------------|-------|----------|-------|----------|---|----|----------|
| | Property is: | Single Fami | у | | Dup | olex | Other □ | | |
| Date: | 12/13/2016 | | - | | | | | | |
| take no responsib | ility for problems d | iscovered after th | e ins | oecti | on da | te, or | e City of Milwaukee, the Redevelopment Authority, and for omissions through error or oversight. The list does Block Grant or HOME programs. | - | |
| Exterior Co | ndition Repo | ort | | | | | | | |
| Location Site | Required Wo | ork | n/a | √ | Yes | | Note/Comments | \$ | Cost |
| | Steps/Handrails | | n/a | V | Yes | | | \$ | |
| | Service walks | | n/a | V | Yes | | | \$ | |
| | Fencing | | n/a | V | Yes | | | \$ | |
| | Parking | | n/a | V | Yes | | | \$ | |
| | Retaining walls | | n/a | V | Yes | | | \$ | |
| | Other | | n/a | | Yes | | | \$ | |
| | Other | | n/a | | Yes | | | \$ | |
| Garage | Singles: repair | | n/a | V | Yes | | | \$ | |
| | Shingles: Roof o | over existing | n/a | V | Yes | | | \$ | |
| | Shingles:Tear of | if & re-roof | n/a | | Yes | V | Assumed - snow covered | \$ | 3,000.00 |
| | Gutters/downspo | outs | n/a | V | Yes | | | \$ | |
| | Flashing | | n/a | V | Yes | | | \$ | |
| | Eaves | | n/a | V | Yes | | | \$ | |
| | Siding | | n/a | V | Yes | | | \$ | |
| | Doors | | n/a | | Yes | V | Both overhead and both service doors | \$ | 1,800.00 |
| | Windows | | n/a | V | Yes | | | \$ | |
| | Slab | | n/a | V | Yes | | | \$ | |
| | Paint | | n/a | | Yes | V | | \$ | 1,250.00 |
| | Electrical | | n/a | V | Yes | | | \$ | |
| | Other | | n/a | | Yes | | | \$ | |
| Porches | Roof | | n/a | V | Yes | | | \$ | |
| | Deck-upper | | n/a | √ | Yes | | | \$ | |
| | Decklower | | n/a | √ | Yes | | | \$ | |
| | Hand/guardrails | | n/a | | Yes | V | On front porch steps | \$ | 300.00 |
| | Ceiling | | n/a | √ | Yes | | | \$ | |
| | Guardrails | | n/a | √ | Yes | | | \$ | |
| | Structural | | n/a | √ | Yes | | | \$ | |
| | Paint | | n/a | | Yes | ✓ | | \$ | 1,500.00 |

n/a Yes 🗸 Repairs at arched openings

\$

500.00

Other

House

| Chimney | n/a 🗸 Yes 🗌 | | \$ |
|------------------------------|-------------|----------------------------|-------------|
| Shingles: repair | n/a ☑ Yes ☐ | | \$ |
| Shingles: Roof over existing | n/a ☑ Yes ☐ | | \$ |
| Shingles:Tear off & re-roof | n/a ☐ Yes ✓ | | \$ 12,500.0 |
| Gutters/downspouts | n/a ☐ Yes ✓ | | \$ 1,250.0 |
| Flashing | n/a ☐ Yes ✓ | | \$ 300.0 |
| Eaves | n/a ☐ Yes ✓ | - | \$ 2,250.0 |
| Siding | n/a ☐ Yes ✓ | Includes sheathing repairs | \$ 10,500.0 |
| Storm Doors | n/a ✓ Yes 🗌 | | \$ |
| Prime ("main") Doors | n/a ✓ Yes 🗌 | | \$ |
| Storm Windows | n/a ☐ Yes ✓ | | \$ 3,500.0 |
| Prime ("main") Windows | n/a Yes 🗸 | | \$ 1,240.0 |
| Paint | n/a Yes 🗸 | Trim and eaves | \$ 2,000.0 |
| Foundation | n/a ✓ Yes 🗌 | | \$ |
| Electrical | n/a ✓ Yes 🗌 | - | \$ |
| Other | n/a 🗌 Yes 🗌 | | \$ |
| Other | n/a Yes | | \$ |
| Other | n/a 🗌 Yes 🗌 | - | \$ |
| Other | n/a 🗌 Yes 🗌 | | \$ |

Exterior: Estimated Cost:* \$ 41,890.00
*average contracted cost. Actual costs may vary. Self help will reduce the amount.

| Interior Coi | ndition Report | | | | | |
|-----------------------|--|-----------------|-------|-------------------------------|---------------------------|----------------|
| | Unit: Entire unit (single family) Upper unit of duplex | | | Lower unit of duplex Other | | |
| Mechanical Heating | Required Work | | | | | |
| licating | Repair/replace boiler | n/a 🔽 🗅 | res 🗌 | | | \$ |
| | Repair radiation | n/a ☑ ` | res 🗌 | | | \$ |
| | Repair/replace furnace | n/a 🗸 🗎 | res 🗌 | | | \$ |
| | Repair ductwork | n/a ☑ ` | res 🗌 | | | \$ |
| | Replace thermostat | n/a ☑ \ | res 🗌 | - | | \$ |
| | Repair/replace grilles | n/a 🗸 🗎 | res 🗌 | | | \$ |
| Flactwicel | Tune boiler/furn. insp ht exchang | gen/a 🔲 🗎 | Yes ✓ | | | \$ 300.00 |
| Electrical | Repair/replace receptacles | n/a 🔲 🗅 | Yes ✓ | _ | | \$ 300.00 |
| | Repair/replace switches | n/a 🔲 🗅 | ∕es ✓ | | | \$ 300.00 |
| | Repair/replace fixtures | n/a 🔲 🗅 | Yes ✓ | _ | | \$ 300.00 |
| | Install outlets and circuits | n/a ✓ \ | res 🗌 | | | \$ |
| | Install outlets and circuits | n/a 🗸 🗅 | res 🗌 | | | \$ |
| | Install outlets and circuits | n/a 🗸 🗎 | res 🗌 | | | \$ |
| | Install outlets and circuits | n/a 🔽 🗅 | res 🗌 | _ | | \$ |
| | Upgrade service | n/a ✓ \ | res 🗌 | | | \$ |
| | Other | n/a 🔲 🗅 | res 🗌 | | | \$ |
| | Other | n/a 🔲 🗅 | res 🗌 | | | \$ |
| Plumbing | Repair/replace kitchen sink | n/a □ \ | ∕es ✓ | | | \$ 500.00 |
| | Repair/replace kitchen sink fauce | ein/a \square | res ⊽ | | | \$ 300.00 |
| | Repair/replace tub | | res 🗌 | | | \$ |
| | Repair/replace tub faucets | n/a \square | res ⊽ | | | \$ 600.00 |
| | Half bathroom off kitchen | n/a 🔲 🗅 | res ⊽ | Complete replacement | nt | \$ 1,750.00 |
| | Repair/replace lavatory | n/a 🗸 🗅 | res □ | | | \$ |
| | Repair/replace lavatory faucet | n/a 🗸 🗅 | res □ | | | \$ |
| | Repair/replace wash tub | n/a 🗸 🗅 | ∕es □ | | | \$ |
| | Repair/replace wash tub faucet | n/a 🗸 🗅 | ∕es □ | | | \$ |
| | Other | n/a 🔲 🗅 | res ✓ | Secure loose pex wa | ter main line in basement | \$ 150.00 |
| | Repair drain/waste/vent piping | n/a 🔲 🗅 | ∕es ✓ | | | \$ 400.00 |
| | Repair water piping | n/a 🔲 🗅 | ∕es ✓ | | | \$ 200.00 |
| | Repair/replace water heater | n/a 🔲 🗅 | ∕es ✓ | Overflow pipe needed | | \$ 75.00 |
| | Other | n/a 🔲 🗅 | res ✓ | Permit | | \$ 85.00 |
| | | | | | | |

n/a Yes V Make tub surround waterproof

Other

500.00

| Windows | | | | | | | |
|----------------|----------------------------------|--------|-------------|----|----------|----------|-----|
| | Replace broken glass | n/a [| √ Y€ | es | | \$ | |
| | Repair or replace sash | n/a [| √ Y€ | es | | \$ | |
| Doors | Repair or replace doors | n/a [| √ Y€ | es | | \$ | |
| Valls/Ceilings | Repair or repl. locks/latches | n/a [|] Ye | es | V | \$ 200 | .00 |
| vans/cenings | Repair or repl. @ defective | n/a [| Y6 | es | V | \$ 2,000 | .00 |
| Paint | | | | | | | |
| | Repair or repl. @ defective | n/a [| Ye | es | ✓ | \$ 1,000 | .00 |
| Fire Safety | Install smoke/CO alarm:bsmt. | n/a [| √) Ye | | П | \$ | |
| | · | II/a L | <u> </u> | :5 | Ш | | |
| | Install smoke/CO alarm: 1st flr. | n/a [| ✓ Ye | es | | \$ | |
| | Install smoke/CO alarm: 2nd flr. | n/a | ✓ Ye | es | | \$ | |
| landrails | Repair/replace defective | n/a [| □ Υ€ | es | 7 | \$ 25(| .00 |
| Stairs | | | _ | | | | |
| loors | Repair defective | n/a [| √ Ye | es | | \$ | |
| Other | Repair defective | n/a [| Ye | es | V | \$ 2,000 | .00 |
| | | n/a [| Y | es | | \$ | |
| | | n/a [| Ye | es | | \$ | |
| | | n/a [| Y | es | | \$ | |
| | | n/a [| | es | | \$ | |

| Interior Cor | ndition Report Unit: Entire unit (single family) | | | | | Lower unit of duplex | | | |
|--------------|--|----------|----------|-----|----------|----------------------|----|----|----------|
| Mechanical | Upper unit of duplex Required Work | √ | | | | Other | | | |
| Heating | Repair/replace boiler | n/a | V | Yes | | _ | | \$ | |
| | Repair radiation | n/a | V | Yes | | | | \$ | |
| | Repair/replace furnace | n/a | V | Yes | | | | \$ | |
| | Repair ductwork | n/a | V | Yes | | | | \$ | |
| | Replace thermostat | n/a | V | Yes | | | | \$ | |
| | Repair/replace grilles | n/a | V | Yes | | | | \$ | |
| | Tune boiler/furn. insp ht exchang | gen/a | | Yes | V | | | \$ | 300.00 |
| Electrical | Repair/replace receptacles | n/a | | Yes | ✓ | | | \$ | 500.00 |
| | Repair/replace switches | n/a | | Yes | V | | | \$ | 500.00 |
| | Repair/replace fixtures | n/a | | Yes | V | | | \$ | 500.00 |
| | Install outlets and circuits | n/a | V | Yes | | | | \$ | |
| | Install outlets and circuits | n/a | V | Yes | | | | \$ | |
| | Install outlets and circuits | n/a | V | Yes | | | | \$ | |
| | Install outlets and circuits | n/a | V | Yes | | | | \$ | |
| | Upgrade service | n/a | V | Yes | | | | \$ | |
| | Other | n/a | | Yes | | | | \$ | |
| . | Other | n/a | | Yes | | | | \$ | |
| Plumbing | Repair/replace kitchen sink | n/a | V | Yes | | | | \$ | |
| | Repair/replace kitchen sink fauce | ein/a | V | Yes | | | | \$ | |
| | Repair/replace tub | n/a | V | Yes | | <u> </u> | | \$ | |
| | Repair/replace tub faucet | n/a | V | Yes | | | | \$ | |
| | Repair/replace toilet | n/a | V | Yes | | | | \$ | |
| | Repair/replace lavatory | n/a | 7 | Yes | | | | \$ | |
| | Repair/replace lavatory faucet | n/a | V | Yes | | | | \$ | |
| | Repair/replace wash tub | n/a | V | Yes | | | | \$ | |
| | Repair/replace wash tub faucet | n/a | V | Yes | | | | \$ | |
| | Unclog piping: | n/a | | Yes | V | | | \$ | 750.00 |
| | Repair drain/waste/vent piping | n/a | | Yes | V | | | \$ | 375.00 |
| | Half bathroom off kitchen | n/a | | Yes | V | Complete replaceme | nt | \$ | 1,750.00 |
| | Repair/replace water heater | n/a | | Yes | V | | | \$ | 1,300.00 |
| | Other | n/a | | Yes | V | Permit | | \$ | 85.00 |
| | Other | n/a | | Yes | | | | \$ | |

| Windows | | | | | | | | |
|----------------|----------------------------------|--------|----------|-----|----------|--|-------------|-----------|
| | Replace broken glass | n/a [| √ | Yes | | | \$ | |
| D | Repair or replace sash | n/a [| √ | Yes | | | \$ | |
| Doors | Repair or replace doors | n/a [| √ | Yes | | | \$ | |
| | Repair or repl. locks/latches | n/a _[| | Yes | V | | \$ | 200.00 |
| Walls/Ceilings | Repair or repl. @ defective | n/a [| | Yes | V | | \$ | 1,000.00 |
| Paint | | | | | | | | |
| | Repair or repl. @ defective | n/a [| | Yes | V | | \$ | 500.00 |
| Fire Safety | | | | | | | | |
| | Install smoke/CO alarm:bsmt. | n/a [| ✓ | Yes | | | \$ | |
| | Install smoke/CO alarm: 1st flr. | n/a [| ✓ | Yes | | | \$ | |
| | Install smoke/CO alarm: 2nd flr. | n/a [| √ | Yes | | | \$ | |
| Handrails | Repair/replace defective | n/a [| √ | Yes | | | \$ | 375.00 |
| Stairs | Daniel defeative | / | _ | V | | | Φ. | |
| Floors | Repair defective | n/a [| √ | Yes | Ш | | \$ | |
| | Repair defective | n/a [| | Yes | V | | \$ | 2,500.00 |
| Other | | n/a [| | Yes | | | \$ | |
| | | n/a [| | Yes | | | \$ | |
| | | n/a [| | Yes | | | \$ | |
| | | n/a [| | Yes | | ÷ | \$ | |
| | | | | | | Interior: Estimated Cost: | \$ | 21,845.00 |
| | | | | | | Total Exterior and Interior Cost:* | \$ | 63,735.00 |
| | | | | | | *average contracted cost. Actual costs may vary. Self help will reduce | the amount. | |
| | | | | | | | | |

Inspected by: Jeff Sporer Date: 12/12/2016

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants *may* be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 W. Mill Road.